



DANGER 240V
DISCONNECT POWER BEFORE
SERVICING UNIT

INSTALLATION INSPECTOR PLEASE NOTE:
THIS PRODUCT HAS PASSED THE INSULATION RESISTANCE TEST AFTER MANUFACTURE. IF THE RESISTANCE READING IS LOW AT INSTALLATION, IT IS PROBABLY CAUSED BY MOISTURE FROM THE ATMOSPHERE BEING ABSORBED BY THE ELEMENTS AFTER THE RANGE HAS BEEN PRODUCED. (PASS AT 0.01 M AS/NZS 3000 WIRING RULES CLAUSE 8.3.6.2).