Service-Bulletin



Cooking appliances

599 528 049

ΕN

built-in cookers/ovens correct assembly of the fat filter

problem: An incorrect assembly of the fat filter with a small rate of air flow (figure 1) extends

remarkably the baking and roasting time. This may appear e.g. with frozen instant meals. According to the producer French Fries need approx. 20 min. With fat filter

approx. 40 min.

reason: Because of the low rate of air flow of the fat filter there will arise behind the deflector a

heat accumulation which will affect the control sensor.

removal of problem: Assemble the fat filter during baking and roasting only as described in the

instructions of use. From these instructions of use you can conclude the baking/roasting temperatures and the baking/roasting times when installing the fat filter.



Fig. 1