
Fitted cooker/oven with illuminated bar in the switch panel

Problem: There have been complaints concerning the „gleaming“ of the illuminated bar upwards between the switch panel and the panel carrier.



Measures from the factory: Conversion to a screened illuminated bar which basically avoids the „gleaming“.

Afer sales service: In case of complaint, apply the adhesive tape with spare part No. 330 573 300/2 across the entire panel width on the top of the appliance. This prevents „gleaming“ upwards.

