

ERROR CODE E50(E58) IN SAHARA HP.

DESCRIPTION:

After finish of drying cycle error code E50(E58) is displayed.

SOLUTION:

Problem is eliminated by Inverter change from 136624020 to 136624021.

SPARE PARTS:

Part Detail	From		To	
	ANC	Q'ty (ea)	To	Q'ty (ea)
Inverter board	136624020	1	136624021	1

MODELS INVOLVED:

PNC	Model name
916096683	T75470AH
916096684	T76485AH
916096685	T76489AH
916096686	T86585IH
916096687	T86589IH
916096693	T86590IH
916096694	T96690IH
916096695	T96699IH
916096696	T96699IH
916096697	T96690IH
916096698	T86590IH
916096699	T86590IH
916096700	T86590IH
916096709	T86589IH
916096710	T86585IH
916096711	T76489AH
916096712	T76485AH
916096713	T75470AH
916096714	T75478AH
916096724	T86585IH

PNC	Model name
916096816	T76480AH
916096817	T76480AH
916096818	T86580IH
916096819	T86590IH
916096830	QW7270
916096831	QW8280
916096832	QW9290
916096834	T76480AH
916096836	TB7050TW
916096837	TWGL5E200
916096838	TWL4E200
916096839	TWSL4E200
916096855	T96699IH
916096856	T96699IH
916096857	T75470AH
916096866	TB7150NTW
916096867	TP8435
916096868	TWSLEEV200
916096869	TP7325
916096870	TP8535

PNC	Model name
916096725	T76489AH
916096726	T76485AH
916096727	T75470AH
916096728	T75478AH
916096736	T86589IH
916096738	TP6040TW
916096745	T75470AH
916096748	T96699IH
916096749	T86580IH
916096750	T76485AH
916096779	T76488AH
916096786	T75472AH
916096792	T96685IH
916096793	T96685IH
916096794	T96685IH
916096795	T96699IH
916096796	T96699IH
916096797	T96699IH
916096810	TR8060TW
916096814	TWSL6E200
916096815	T75470AH

PNC	Model name
916096873	TWGLES7000
916096877	T86589IH
916096878	TW7768
916096879	TW5457F
916096880	T86590IH
916096884	T76484EIH
916096888	T76487AH
916096890	T7648EXAH
916096891	T75472AH
916096901	T76484EIH
916096902	T75470AH
916096904	TWSLEP200
916096906	T76484EIH
916096907	T76484EIH
916096908	T76484EIH
916096909	T76486EIH
916096911	TP6010TW
916096975	T86580IH
916096976	T75470AH
916096993	T75470AH

REVISIONS:

Revision	Date	Description	Author	Approved by - on
00	04/2012	Document Creation	KL	PZ – 05/2012