

SERVICE BULLETIN REFRIGERATION

DOOR MAGNET REPLACEMENT

DESCRIPTION:

The lighting is not switch off due to the magnet is missing from the door and the relay can not detect it.

SOLUTION:

To solve problems in the field replace the magnet (224 00 76-03 / 0) into the door end cap.





2. Sign the door end cap where you found the relay position



3. Drill the end cap in 30 mm deeply with $\emptyset 6$ mm spiral drill



4. Take a piece of insulation rubber into the drilled hole



5. Take the magnet into the drilled hole and push until is aligned with the door end cap





