



SERVICE BULLETIN

Dometic GmbH, In der Steinwiese 16, D-57074 Siegen

MDxxxx

Faulty microswitch

If the error message „Error 2“ is shown, in most cases the problem is the microswitch. The little metal sheet on the microswitch (see picture) is broken. Please check if the exchange of the microswitch, spare part number 414 0050-55/2, is enough to solve the problem before exchanging the electronic or the motor.



Microswitch 414 00 50-55/2