


RMD 8501/8505/8551/8555, RMDM 8501/05/51/55,
RMDT 8501/8505/8551/8555

Ice formation on the freezer door

In above mentioned fridges condensed water can arise on the decoration panel and the door locking device can be frozen.

This new Servicekit will solved this problem.

The Servicekit, spare part no. 241 2350-95/7, contains a isolation strip, an adhesive tape, and a redesign lock.



Uninstalling decoration panel

Version with cover strip



Version without cover strip / frameless door

