

CDADB, CDADBT (Air ventilation box for air conditioners)

Fastening of air ventilation box

If the air ventilation box is tightened with **more** than 2,5 Nm, the vibration of the compressor will be transmitted to the roof of the vehicle and annoying noise may occur.

If the air ventilation box is tightened with **less** than 2,5 Nm, then the speed of the ventilator will lead to high vibration in the frame of the air ventilation box.



Please note! The air ventilation box should be tightened with 2,5 Nm.

