

SERVICE BULLETIN REFRIGERATION

Ventilation fan replacement

DESCRIPTION:

Ventilation fan 2081659050 is no longer possible to order. It was replaced by ventilation fan 4055355665 which does not contain cover.



SOLUTION:

Cover from old ventilator assembly must be reused while ventilator exchange.

REVISION:

Revision	Date	Description	Author	Approved by - on
00	04/2016	Document Creation	Marzena Kosecka	

EN SDT – MK 1/1 599 79 69-76 Rev.00