

WINE-COOLER TO COLD
DESCRIPTION:

Wine cooler temperature can go to below 0 °C.

SOLUTION:

Replace the NTC sensor. The new NTC sensor has more insulation.

SPARE PART CODE:

New spare part code	Description
4055389995	Sensor, MF52E

Use the following QES codes when reporting the service order:

Component	407
Defect	28

MODELS:

PNC	Model
923421076	ERW0273AOA
923421077	ERW0673AOA
923421078	ERW1573AOA
923421079	SWB61501DG
923421080	SWB63001DG
923421081	SWB66001DG
923421088	SWE61501DG
923421089	SWE63001DG
923421090	SWE66001DG

REVISION:

Revision	Date	Description	Author	Approved by
00	04/2019	Document Creation	Anna Grimlund	Yurii Ravskyi