



## EC9 ERROR APPEARING ON THE DISPLAY

### DESCRIPTION:

During the cycle EC9 error can appear on the WM display – user is not able to use WM

Error can occur on the FL WM with EWX14931 BASIC VERSION

**There is no needs to exchange PCB**

### SOLUTION:

Use SideKick to reprogram main electronic board with the latest software.

**IMPORTANT: Update Sidekick before performing this action to have the latest required update available.**

### QES CODE:

During the intervention please use work code XXX and:

Component	G10	607 Main control PCB
Defect	G10	31 Software fault

### MODELS INVOLVED:

FL WM with EWX14931 BASIC VERSION.

**Table 1** in attachment provides a list of PNCs.

FL WM produced before SN922

### REVISION:

Revision	Date	Description	Author	Approved by - on
00	07/2019	Document Creation	Marcin Pluta	Adam Słoma – 01.07.2019