

SERVICE BULLETIN REFRIGERATION FS Freezer

ICE BUILD UP ON THE COLD MODULE

The cold module in the top of the freezer is covered in ice



SOLUTION:

Check the connection and the assembly of the fan unit at the back of the cold module. There are two possible problems:



1. Fan is not connected



2. Fan unit is not in the right position.

Use the following QES Codes when reporting the Service Order:

Component	108,169,331,401,404,701,703
Defect	10,80,81,87,

MODELS INVOLVED:

Freestanding freezers FzFF200 925 041 4xx and FzFF250 925 052 7xx, 925 052 8xx

REVISION:

Revision	Date	Description	Author	Approved by - on
00	10/2019	Document Creation	Anna Grimlund	Attila Héri/ Judit Hudákné Szabó