



QUICK CYCLE LASTS 50 MIN

DESCRIPTION:

In Domodossola* 14PS platform it is possible that Quick Cycle is bugged

Outcome: Quick Cycle is extended to 50 minutes

There is no need to exchange PCB

SOLUTION:

Use SideKick to reprogram main electronic board with the latest software.

IMPORTANT: Update Sidekick before performing this action to have the latest required update available.

QES CODE:

During the intervention please use work codes:

Component	F10	607 Circuit Board/Main control PCB
Defect	F10	31 Software fault

In the section for Tech. Comments insert:

Main board software update to solve “Quick Cycle bug” – SB no.: 599 83 53-27

MODELS INVOLVED:

DW with PB150

Dishwashers produced before SN005 (up to week 5 of 2020)

PNC	911514061	911516383	911524096	911536398
911514046	911514062	911516384	911524097	911536449
911514047	911514063	911516389	911526375	911544040
911514048	911514064	911516390	911526376	911544041
911514049	911514065	911516392	911526380	911546163
911514050	911516377	911516393	911536390	911546164
911514051	911516378	911516394	911536391	911546165
911514052	911516379	911516396	911536392	911546166
911514053	911516380	911516400	911536394	911546167
911514057	911516381	911524094	911536395	911546168
911514058	911516382	911524095	911536396	

REVISION:

Revision	Date	Description	Author	Approved by - on
00	02/2020	Document Creation	Marcin Pluta	Sebastian Dziura 13-02-2020