




Door replacement

DESCRIPTION:

Doors included in left column of Tab.1 will not be available anymore because of quality issues related to its innerliner shape.

SOLUTION:

New doors are created to replace previous one with changed innerliner. Due to new innerliner door shelf shown in the picture Pict.1, which could be found in some appliances will not be possible to mount.




Pict.1 The drawer which could not be mounted in new door

The difference between old and new doors is visible (Pict.2.)

A.

B.



Pict.2 A- the old door; B- the new door

SPARE PART NUMBER:*Tab.1 Old doors codes and corresponding new doors codes*

Old spare part code	New spare part code
140053682690	140201005216
140118067150	140201005224
140118067184	140201005232
140118067457	140201005265
140118067499	140201005257
140118067507	140201005240
140118067705	140201005331
140118067754	140201005638
140118067762	140201005323
140118067770	140201005281
140118067788	140201005307
140174906051	140201005307
140174906077	140201005646
140174906101	140201005414
140174906119	140201005406
140174906127	140201005398
140174906135	140201005380
140174906317	140201005448
2109007688	140201005018
2109007712	140201005059
2109007720	140201005075
2109007738	140201005091
2109007746	140201005109
2109007845	140201005596
2109007852	140201005604
2109007860	140201005034
2109007902	140201005042
2109007928	140201005083
2109007936	140201005117
2109007944	140201005125
2109007951	140201005133
2109008355	140201005026
2109008462	140201005141
2109008488	140201005067
2801830825	140201005166
2801830908	140201005158
2801840444	140201005190
2801840451	140201005208

REVISION:

Describe the revisions using a table with borders and bold headlines in lowercase with initial capital:

Revision	Date	Description	Author	Approved by - on
00	03/2020	Document Creation	Natalia Przała	