Technical Bulletin Nº CB1054.docx

Issue: 1 Date: 10/20

Telescopic runners/slides broken welds.

There has been an issue with a weld on the bracket which holds the runners in place to the side rack.

The factory is 100% checking stock to ensure good parts are supplied with products.

Please arrange for a replacement part to be sent out to the customer. Contact service.nswparts@electrolux.com.au with your request. Instructions on how to install telescopic runners are provided with the parts.

See below for part numbers.



Double extension A18158301
Model
EVE626DSD
EVEP626DSD
EVEP626SD
EVE614DSD
EVE614SD
EVE616DSD
EVE626DSD
EVE636DSD
EVEP614DSD
EVEP614SD
EVEP616DSD
EVEP618DSD
EVEP626DSD
EVEP626SD
EVEP916DSD
BPK722910M (Export Model)
BPK722910M - IS (Export Model)
BPK822910M (Export Model)
BPK822910M - IS (Export Model)

Single extension A18158303
Model
CVE602SA
WFE914SC
WFE9143C WFE915SD
WFE916DSD
WFE946SC
WFE946SD
WFEP915SC
WFEP917DSD
WVE606SA
WVE607S
WVE615SH
WVE615WH
WVE616SC
WVE616SC-U
WVE616SCX
WVE617DSC
WVE617DSC-U
WVE636SC
WVE677SCX
WVEP617DSC
WVEP617DSC-U
WVEP618DSC
WVEP618DSC-U
WVEP627DSC
WVEP916SC
WVEP917DSC
WVEP917DSC-U
EFE914DSD
EFEP916DSD
EFEP956DSD
EVE916SD-MEA
WVE617S