



COMBI MW ovens - Condensation inside door during cooking function


DESCRIPTION:

During usage of combi oven, condensation is appearing inside oven door (between the glasses).



SOLUTION:

The main reason for this kind of failure is lack of tightness between the door inner cover and small inside glass glued to it:



The solution is to replace full inner cover by new spare part number with improved adhesion between plastic cover and glass: **561626486**

SPARE PART NUMBER:

Old spare part code	New spare part code	Description
5616264528	561626486	-

QES CODE:

EN [AS] – [BSP]

1/4

599 856 511 Rev.00

During the intervention, please use work code 11 and:

Component	232 Door panel (inner)
Defect	15 Condensation

Corrective action implemented (improved adhesion between cover and glass) from serial number: 106 XXXXX.

MODELS INVOLVED:

Combi MW built in ovens:

PNC	MODEL DENOM
944066047	EVY7800AOX
944066048	EVY7800AAX
944066052	ZKC44500XA
944066060	EVY7600AOX
944066065	ZKC44510XA
944066106	EVY7800AAV
944066119	EVY9760AOX
944066137	EVY97800AX
944066256	ID_704962
944066352	EVY7800AAX
944066366	EVY7810AAV
944066376	KM1840310X
944066438	AKM7610AAX
944066468	KME561000M
944066469	KME761000B
944066470	KMK761000W
944066478	EKM700CX
944066479	EKM700CW
944066484	KMM761000M
944066490	ZKK47902XK
944066501	JLBICO431
944066559	ZKC47902BU
944066567	IKC6500-RF
944066571	EVY7600AAX
944066600	OCB451NX
944066611	OOM1000CZ
944066635	OOM700CZ
944066684	KMK868000B
944066714	EB4PL90KMS
944066715	CMB6750_OS
944066722	KMK861000B
944066722	KMK861000B
944066734	KME761000W
944066750	KMK861000B
944066786	KME968000M
944066787	KMK968000M
944066847	KEE768080B

PNC	MODEL DENOM
944066637	COM700CV
944066642	VKL6E40X
944066648	KVLDE40X
944066649	KVLBE00X
944066650	CKM1000CX
944066653	KMK561000M
944066654	CME565000M
944066655	EVY7800AAX
944066660	BO4GEMKM
944066665	KME968000M
944066668	KMK968000M
944066670	KMK861000B
944066683	KME768080M
944066785	KMF768080M
944066807	BFB8000QM
944066696	KMK968000T
944066697	KMK768080B
944066699	SMAKSACMX
944066700	KULINACMX
944066701	SMAKSACMX
944066702	KULINACMX
944066712	EB4PL90KCN
944066713	EB4PL90KSP
944066716	JBKM131D0
944066719	PCM43102X
944066729	KMK761000M
944066731	KME761000M
944066732	KME761000B
944066733	KMK761000W
944066735	QCK8070X
944066739	KMK565000M
944066741	OOM1000CZ
944066742	KVLAE00WT
944066743	CKM700CX
944066744	CKM700CV
944066746	OOM700CZ
944066747	COM700CX

944066847	KEE768080B
944066848	KES768080M
944066848	KES768080M
944066061	EVY7800AAX
944066439	KM840310MM
944066483	KMR761000M
944066493	IKC680RF
944066738	QCK8070W
944066756	ZVEHM5X1
944066929	JBKM131D2
944066930	PCM43103X
944066380	KME861000M
944066612	EVL8E00X
944066628	EVL8E00Z
944066643	KVLAE00WT
944066644	VKL8E00X
944066646	VKL8E00V
944066647	VKL8E00Z
944066651	EVL9E00WX
944066705	LAM7003
944066725	KME861000M
944066726	KMK861000M
944066751	FVENM6X2
944066791	JLBICO432
944066882	KMK968000M
944066883	KMK968000M
944066058	EVY7600AOX
944066178	JBKM131D5
944066271	PCM43100X
944066375	EVY7800ZOZ
944066379	KME861000M
944066384	KME561000M
944066394	KMK861000M
944066395	KMK861000M
944066440	KMK761000M
944066448	KMK361000M
944066449	KMS361000M
944066450	KME761000M
944066451	KME761000B
944066463	KMK761000M
944066464	KMK561000M
944066467	KME761000M
944066471	KME761000W
944066485	KMR761000W
944066489	ZKK47901XK
944066492	QCK8070X
944066494	IKC670RF

944066748	COM700CV
944066749	CKM1000CX
944066754	ZVENM7X1
944066755	ZVENM6X1
944066761	ZVENM5X1
944066762	ZVEIM5X1
944066763	ZVEKM7X1
944066764	ZVEKM6X2
944066765	ZVEKM6K2
944066766	ZVEIM6X2
944066767	ZVEEM6X1
944066768	ZVEKM6X1
944066769	ZVEKM8X1
944066770	ZVEKM5X1
944066771	ZVEWM5X1
944066774	KMK968000M
944066779	KVLBE00X
944066780	KVLBE00X
944066784	KMK968000T
944066788	KMK768080B
944066789	ZVENM6X2
944066796	ATM7610AX
944066798	CBM6750.0S
944066799	KMK565000X
944066800	KME565000M
944066801	ZVENM7K1
944066802	BFB9000QM
944066803	BHB9000QM
944066805	BBB9000QB
944066808	BBB8000QB
944066865	KME768080M
944066811	KEK965090M
944066813	KEK965090T
944066909	BFB8000QM
944066935	KME768080M
944066682	KMK768080M
944066782	KMK768080M
944066821	KMK765080B
944066806	BHB8000QM
944066810	QCK597X
944066828	KMK96708PT
944066829	BBB5000QB
944066830	KVLBE08WX
944066833	EVL8E08WZ
944066839	KMK968000M
944066840	KMK968000B
944066843	KMK968090B

944066495	KMS761000M
944066516	EB4SL90KCN
944066517	EB4SL90KSP
944066532	KVLAE00WX
944066534	KMK36100MM
944066535	FINSMACMB
944066539	SMAKSACMX
944066542	CD710M
944066544	SMAKSACMX
944066545	SMAKSACMB
944066546	KMK761000W
944066547	KME761000W
944066550	KMK761000M
944066551	EB4GL90KCN
944066552	EB4GL90KSP
944066554	KMK761000M
944066562	QCK8070W
944066568	KMK861000M
944066572	KME565000M
944066573	KMK565000M
944066576	CMK56500MM
944066577	KMS565000M
944066578	CD511M
944066579	FINSMACMB
944066580	FINSMACMB
944066581	SMAKSACMX
944066582	SMAKSACMB
944066583	SMAKSACMB
944066584	KMK565000M
944066588	KULINACMX
944066589	KULINACMX
944066590	KULINACMX
944066596	SMAKSACMX
944066597	KULINACMX
944066601	LAM7002
944066603	KVLBE00X
944066616	EVL6E40X
944066618	KVLAE00WT
944066632	CKM700CX
944066633	CKM700CV
944066636	COM700CX

944066820	KMK765080M
944066853	EVL8E08WX
944066854	VKL8E08WX
944066855	VKL8E08WV
944066856	VKL8E08WZ
944066859	KME968000M
944066860	ZVEXM8KI
944066866	BHB6000QM
944066867	BBB6000QB
944066868	BFB6000QM
944066870	COM806CX
944066872	CKM806CV
944066874	SMAKSACMX
944066875	KULINACMX
944066876	FM4EP
944066877	SMAKSACMX
944066878	SMAKSACMX
944066879	SMAKSACMX
944066880	SMAKSACMX
944066884	KVLBE00X
944066888	KVLBE00X
944066891	IKC670RF
944066892	ZVENM6K2
944066894	KME761000B
944066895	QCK8070X
944066896	BHB5000QM
944066897	OOM1010CZ
944066898	KMK76808PT
944066899	CKM700CX
944066900	CKM700CV
944066901	OOM705CZ
944066902	COM700CX
944066903	COM700CV
944066904	CKM1000CX
944066905	BFB9000QM
944066906	BHB9000QM
944066907	BBB9000QB
944066846	CD780M
944066910	BBB8000QB
944066911	BBB5000QB

REVISION:

Revision	Date	Description	Author	Approved by - on
01	11/2021	Document Creation	P. Narewski	