

SERVICE MODE ACTIVATED ACCIDENTALLY

DESCRIPTION:

Consumers may activate service mode by mistake, consumers claim:

- LED light is not working
- Only the yellow LED is blinking on the electronics
- Compressor is not running

Service mode is activated by pressing the 2 buttons at the same time for about 5 seconds. This problem affects all appliances with internal ERF501X electronics.

SOLUTION:

Exit service mode by pressing the 2 buttons at the same time for about 5 seconds.



QES CODE

Component	152
Defect	31

MODELS INVOLVED:

All appliances with internal ERF501X electronics

REVISION:

Revision	Date	Description	Author	Approved by - on
00	02/2022	Document Creation	Anna Grimlund	Diána Szabo