



- 1.Compressor overload protection
- 2.PTC or TSD starter
- 3.Compressor main winding
- 4.Compressor starting winding
- 5.Electronics
- 6.Operating capacitor (optional)