



|      |        |   |    |    |     |     |     |     |     |     |     |
|------|--------|---|----|----|-----|-----|-----|-----|-----|-----|-----|
| OVEN | 0      | 0 | 36 | 72 | 108 | 144 | 180 | 216 | 252 | 288 | 324 |
| POS. | 8 - P8 |   |    |    |     |     |     |     |     |     |     |
|      | 7 - P7 |   |    |    |     |     |     |     |     |     |     |
|      | 6 - P6 |   |    |    |     |     |     |     |     |     |     |
|      | 5 - P5 |   |    |    |     |     |     |     |     |     |     |
|      | 4 - P4 |   |    |    |     |     |     |     |     |     |     |
|      | 3 - P3 |   |    |    |     |     |     |     |     |     |     |
|      | 2 - P2 |   |    |    |     |     |     |     |     |     |     |
|      | 1 - P1 |   |    |    |     |     |     |     |     |     |     |



WIRING DIAGRAM