



OVEN	0	0	36	72	108	144	180	216	252	288	324
POS.	0	36	72	108	144	180	216	252	288	324	
8 - P8											
7 - P7											
6 - P6											
5 - P5											
4 - P4											
3 - P3											
2 - P2											
1 - P1											



WIRING DIAGRAM