



SWITCHING DIAGRAM

POSITIONS	1	2	3	4	5	6	7	8	9	FUNCTIONS
0		X				X				0° ∠
1						X	X	X		36, 00° ∠
2	X	X				X	X	X		72, 00° ∠
3	X		X		X	X	X			108, 00° ∠ ECO
4	X					X	X	X		144, 00° ∠
5						X	X	X		180, 00° ∠
6			X	X		X	X	X		216, 00° ∠
7	X		X	X		X	X	X		252, 00° ∠
8	X	X		X		X	X	X		288, 00° ∠
9	X	X				X	X	X		324, 00° ∠