

Service Bulletin

Concerning : Compact Steam Combi and Classic from Schwanden

Period: Appliance prior to serial number 7 35 30 888

Problem : Milky condensation on the interior door plates

Cause: Exhalation of silicone material creates a milky white condensation on the interior plates.


Affected components:

New glass retainer spare parts test 315 6926 03


Solution: After cleaning the interior plates, the glass retaining profile must be replaced with the spare parts set 315 69260 03 in order to avoid the continued exhalation of the old glass retaining profile.

Peculiarities :

ANC old: 315723500/01



ANC new: 315869900/01



in the fitted condition:

