

REPLACEMENT VERTICAL HANDLE

As a result of quality problems due to detaching or breaking of the side caps of the handle, it is possible to replace this handle with a new one as indicated in the Tab. A.

The affected appliances that feature the previous vertical handles are indicated in Tab. B.

PART NOS.:

Tab. A

Previous handle part no.	New handle part no.
2251284036	2236290017
2251284135	2236290017

AFFECETD MODELS:

Tab. B

PNC	Date	Model	Brand
92287468200	20030606	770/779	Lloyds
92287665800	20020622	463.495 2/8070	Privileg
92287665900	20021213	667.603 5/40035	Privileg
92287665901	20030530	667.603 5/40174	Privileg
92287666300	20030606	770/574	Lloyds
92287765800	20020625	916.755 2/8071	Privileg
92287765900	20020610	756/393	Lloyds
92287766800	20021213	556.762 3/40036	Privileg
92287766801	20030530	556.762 3/40173	Privileg
92287768300	20030606	770/736	Lloyds
92387469000	20021206	490.662 4/40018	Privileg
92387469001	20031017	490.662 4/40319	Privileg
92387550300	20021129	681.262 2/40016	Privileg
92387550301	20030613	681.262 2/40250	Privileg
92387650200	20021213	486.024 3/40017	Privileg
92387650201	20030919	486.024 3/40318	Privileg