

Service-Bulletin**3110**Reg. No. 346/94

Caravan appliances**Ignition problems-piezoignitor**

If there are ignition problems concerning new appliances you have to check whether the ignition cable is connected under pressure with the gas supply pipe.

The ignition cable has to be laid freely as otherwise insulation defects are possible.