


SERVICE BULLETIN

Dometic GmbH, In der Steinwiese 16, D-57074 Siegen

RM 7601/05/51/55, RM 7801/05/51/55

Fixing of cooling unit

If the cooling unit of a 2-door fridge from the production in Siegen has to be exchanged, from now on the fixing brackets for the cooling unit must be fixed with stainless steel rivets.



241 2559-82/1
Blind rivet D=4,8x11mm, stainless steel,
20 pieces