

FAULT CODES ON SIDE BY SIDE ICON APPLIANCES

Please find below the fault codes that can flash on the various displays of the Side by Side ICON appliances for 45 seconds after the switching on:

FAULT CODES		DESCRIPTION
FREEZER DISPLAY	DISPLAY COOLER	
2		Freezer temperature sensor interrupted
3		Freezer temperature sensor short-circuited
	2	Cooler temperature sensor interrupted
	3	Cooler temperature sensor short-circuited
E	F	Evaporator ventilator faulty

In case of simultaneous faults, the fault codes will be displayed alternatively.