

SERVICE BULLETIN

Dometic GmbH, In der Steinwiese 16, D-57074 Siegen

RM 7605, RM 7655, RM 7805, RM 7855, RM 8405, RM 8505, RM8555, RMS 8405, RMS 8465, RMS 8505, RMS 8555, RML 8555 AES-electronics

Fixation of burner cover at the cooker sheath

The burner cover is fixed with a screw (3,9x9,5mm) at the cooker sheath.
After service cases this screw had to be fixed again in cause of approval and operation.

