

Insight cookers Motala PNC 947 with OVC2000 electronic

Safety information !

Risk for short circuit

An insulation house 330417501/5 must be assembled on the receptacle for the earth cable which is assembled on the OVC2000 circuit board.

This must be done because the distance between earth and phase on the OVC2000 board is too short. It's a risk for short circuit.

This is valid for:

- Single oven cookers with serial number from 734 to 841.
- Double oven cookers with serial number from 813 to 841.

