


SERVICE BULLETIN

Dometic GmbH, In der Steinwiese 16, D-57074 Siegen

RM 7XX0, RM/S/L 8XX0 with battery igniter

Ignition failures at fridges with battery igniter

If ignition failures occur at the above mentioned fridges and cleaning the burner or exchanging the igniter's battery does not solve the failure, use the new ignition plug (292 3626-10/1) and the insulating tubing (293 5712-01/4) for the ignition cable.



old ignition plug

new ignition plug 292 3626-10/1



Insulating tubing for ignition cable 293 5712-01/4