

SERVICE BULLETIN

Dometic GmbH, In der Steinwiese 16, D-57074 Siegen

RMD 8501/8505/8551/8555

Insulation strip for door locking device in freezer compartment

In above mentioned fridges condensed water can arise on the decoration panel and the door locking device can be frozen.

In this cases please install insulation strip 293 5688-21/4.

Version with cover strip



Version without cover strip / frameless door



Insulation strip 293 5688-21/4

