

Problems with door open detection sensor

Description of problem

Sometimes in the new models that use an infrared sensor to establish whether the door is open or closed, the sensor fail to identify the door position correctly.



This only occurs when the door opening direction on the appliance is inverted.

Solution

To solve this problem, attach a label to the shelf near the sensor.

User Interface

Shelf with label



Spare parts

Label 2620130019



Revisions

Revision	Date	Description	Written by	Approved by - on
00	02 / 2012	Document creation	A.D.L.	