

SET TIMER FAILURE DUE TO A WRONG CONNECTION WITH OVER VOLTAGE (400V)

FAULT:

Display no function after power supply.

DESCRIPTION:

When the Set Timer is wrong connected to 400V the capacitor will be blown like you can see in the picture. The timer will still be working for some minutes, after a short time the display will become black and the resistor R31 will be burned.



HDC05559.JPG

Fig. 1

MODELS INVOLVED:

Models where are used the Timer SET Code:

387 21 08-22/4, 387 21 08-62/0, 387 21 08-42/2, 387 21 08-82/8, 387 21 08-72/9
(see models linked to the spare parts codes).

NOTE:

This intervention of the service is not included in the appliance warranty.

REVISION:

Revision	Date	Description	Author	Approved by - on
00	05/2012	Document Creation	FV	