

## NEW PRESSURE SENSOR


### DESCRIPTION:

A new pressure sensor, without a support is replacing an assembly with support.

### SOLUTION:

For 3 types of dishwashers (60/45/55) there are 3 different ANC codes. The difference is only on the length of the hose, that is different for each platform. The other components of the assembly are the same. In case of exchange, the following components need to be changed:

### SPARE PARTS:



**SPARE PARTS :**

<b>Spare part description</b>	<b>Spare part number</b>
analogic pressure switch,complete,D2 45	1174745008
analogic pressure switch,complete,D2 55	1174745206
analogic pressure switch,complete,D2 60	1174745107

**MODELS INVOLVED:**

All PNCs/Models of 60cm, 45cm, 55cm are involved

**REVISIONS:**

<b>Revision</b>	<b>Date</b>	<b>Description</b>	<b>Author</b>	<b>Approved by - on</b>
00	06/2012	Document Creation	WO	PC