

CONDENSATION ON THE DOOR GLASSES DURING COOKERS PERFORMANCE

PROBLEM DESCRIPTION:

Condensation on the door glasses during cooking in the oven. It can be disturbing for the end customer.

CAUSE OF THE CONDENSATION:

Changes in the ventilation system of the oven.

SOLUTION:

By customer dissatisfaction due to condensation on the door glasses please use a new top cover with spare part code 561603301/4.

That spare part is fitting only appliances without mechanical child lock.

COMMENTS:

New solution is under testing phase (new top cover with additional cut out for the child lock).

By claims regarding condensation on the door please use in QES system the component code 207 (door trim) and the defect code 15 (condensation).

PROCEDURE:

1. Remove the old top cover from the door by pressing the side hooks of the cover and lifting



HDC05927.JPG

Fig. 1

2. Insert the pyro top cover by pressing it and adjusting the inner clips to the slots in the door column.



HDC05929.JPG

Fig. 2

TOP COVER CODE 561603301/4



HDC05928.JPG

Fig. 3

MODELS INVOLVED:

PNC	MODEL	BRAND	COUNTRY
940002601	EKC6030BOW	Faure	GR
940002605	FEH60P2101	Electrolux	CH
940002606	ZCV6602MW	Zanussi	BE GR LU ES CH
940002607	ZCV6602MW	Zanussi	CH
940002609	FCV6601MWC	Faure	FR
940002611	FCV6601MSC	Faure	FR
940002612	FCI6600MWC	Faure	FR
940002618	FEH60G2101	Electrolux	CH
940002620	EKC6430AOW	Electrolux	BY CZ EE KZ LV LT PL RU SK UA
940002621	EKC6450COS	Electrolux	FR
940002623	EKC6450BOX	Electrolux	BE LU
940002624	FHH6886-GK	Electrolux	CH
940002625	FEH60G3101	Electrolux	CH
940002626	EKC6450AOX	Electrolux	BY CZ EE GR KZ LV LT PL RU SK SI UA
940002627	EKI6450AOX	Electrolux	BY BE CZ EE KZ LV LT LU PL RU SK SI UA
940002634	30006VL-WN	AEG Electrolux	AT BE DE GR LU
940002635	40006VS-WN	AEG	AT DE GR
940002636	40006VS-MN	AEG Electrolux	DE
940002637	47056VS-WN	AEG	AT BE HR CZ EE DE HU KZ LV LT LU RU SK SI UA
940002638	47056VS-MN	AEG Electrolux	AU BE HR CZ EE DE HU KZ LV LT LU PL RU SK SI UA
940002640	47036IU-MN	AEG Electrolux	AT BE HR CZ EE DE HU KZ LV LT LU PL RU SI UA
940002642	EKC6450AOW	Electrolux	BY CZ EE GR KZ LV LT PL RU SK SI UA
940002645	ZCE6601MW	Zanussi	GR
940002646	EKS6030AOW	Electrolux	GR
940002647	47056VS-MN	AEG	GR
940002648	47056VS-WN	AEG	GR
940002649	EKC6150AOW	Electrolux	BY HR CZ KZ PL RU SK UA
940002650	EKC6150AOX	Electrolux	BY CZ KZ PL RU SK SI UA
940002651	EKC6430AOX	Electrolux	BY HR CZ EE KZ LV LT PL RU SK UA
947941002	EKC60408W	Electrolux	SE
947941452	EKD60767X	Electrolux	DK SE
947942452	QSI6280W	Husqvarna Electrolux	SE
947942454	QSI6280X	Husqvarna Electrolux	SE
948904009	EKC603602X	Electrolux	IE GB
948904010	EKC607601X	Electrolux	IE GB
948904017	EKC607601W	Electrolux	IE GB
948904220	EKC603600K	Electrolux	IE GB
948904222	EKC603601X	Electrolux	IE GB
948904225	ZCV661MW	Zanussi	IE GB
948904226	ZCV661MWC	Zanussi	IE GB
948904228	ZCV662MWC	Zanussi	IE GB
948904231	ZCV662MXC	Zanussi	IE GB
948904232	ZCV662MNC	Zanussi	IE GB
948904233	ZCV663MWC	Zanussi	IE GB
948904234	ZCV663MXC	Zanussi	IE GB
948904410	49332I-MN	AEG Electrolux	GB
948904411	49002VMN	AEG Electrolux	SE GB
948904412	ZCV621MW	Zanussi	GB

REVISION:

Revision	Date	Description	Author	Approved by - on
00	11/2012	Document Creation	FV	