

## **SERVICE BULLETIN**

Dometic GmbH, In der Steinwiese 16, D-57074 Siegen

---

**RM 5310/30/80, RM 8xx1/5, RMS 8xx1/5, RMD 8xx1/5, RMDT 8xx1/5**

### **Fixing of cooling unit**

In cause of high vibration during the journey bad placed rivets of the cooling unit can be loosen.

In such cases please use only the kit 241 2559-80/5 which is shown on the bottom to fix the cooling unit.

For single door fridges use one fixing clamp and for double door fridges/freezers please use two fixing clamps, also if only one rivet is loosen.

Please send a separate invoice with all datas to the Dometic GmbH.  
For each case a fixed price of 20,00€ net can be charged.



Kit 241 2559-80/5, 2 fixing clamp und 4 rivets