

THE TIMER LOCKS IN CERTAIN POSITIONS (WM - Z805)

Sometimes during a washing cycle the timers (AKO) with:

Cod. 40550 57-29/5 and Cod. 40552 46-79/9

lock in positions corresponding to the various drainage stages of the cycle, and continue to power the drain pump.

Proceed as follows:

- Remove the drain pipe from the installation and check drainage flow.

if it is all in order

- Check the pressure chamber circuit

If, after carrying out these two checks, the circuits are working perfectly then intervene on the Timer.

REVISIONS:

Revision	Date	Description	Author	Approved by
00	10/2013	Document Creation	DMM	XX – 0X/201X