



Positioning of protection foil on OVC3000 boards in microwave appliances

DESCRIPTION:

Residual microwave radiation may cause malfunction of OVC3000 power boards.

SOLUTION:

To prevent this, factories have implemented additional protection foil to insulate vital components on the power board. The foil is available as separate spare part 5550593023, and should be used in all cases of OVC3000 replacement in microwave appliances.



Foil should be placed on the bottom side of the board, 45mm from the edge, as seen on pictures above

MODELS INVOLVED:

This service bulletin is related to all compact microwave appliances with OVC3000 power board.

REVISION:

Revision	Date	Description	Author	Approved by - on
00	02/2014	Document Creation	Marcin Kobialka	Stefan Baumgartner
01	07/2015	5550593015(60x60)-> 5550593023(91x60)	Tomasz Hyży	Grzegorz Omański