

Clock issue**IMPLEMENTATION DATE:** 2014-03**MODELS:** ELECTROLUX-AEG/HUSQUARNA - BUILT-IN SUPER AUTOMATIC COFFEE MACHINES:

Brand	Model	PNC	SN
AEG	PE4541-M	942401209	95.00 - 0132272092
AEG	PE4542-M	942401211	95.00 - 0132272093
AEG	PE4551-M	942401210	96.00 - 0132273085
HUSQVARNA	QCA6051X	942401212	96.00 - 0132273086

DESCRIPTION:

Due to weakness of software to manage the clock time, the codes of the LCD (DISPLAY) PCBs have to be replaced. To solve the problem, order the corresponding codes:

Replace the old LCD (DISPLAY) PCB code: 4055254108 with the new one: **4055276382** for:

AEG	PE4541-M	942401209	95.00 – 0132272092
AEG	PE4542-M	942401211	95.00 – 0132272093

Replace the old LCD (DISPLAY) PCB code: 4055254132 with the new one: **4055276119** for:

AEG	PE4551-M	942401210	96.00 - 0132273085
HUSQVARNA	QCA6051X	942401212	96.00 - 0132273086

Codes are fully interchangeable.

Revision	Date	Description	Author	Approved by - on
00	03/2014	Document Creation	BLANKA KUCHARSKA NICOLA PADULA	B.K. 2014-03

IT0345/2014