

SERVICE BULLETIN

Dometic GmbH, In der Steinwiese 16, D-57074 Siegen

RGE 3000, RMD/T 85xx, RML 8330, RML 855x, RMSL 850x, RML 933x, RML 943x, T150GE

Burner exchange

Some customers have complained the noise level of the new burner from serial number 401xxxxx on.

Because of that Dometic Siegen offer an exchange of the burner including nozzle (KZ16) for above mentioned fridges between serial number 401xxxxx and 443xxxxx.

The old burner has no safety issues. It is just a reaction of subjective impressions of our customers.

Please contact fridge-check@dometic.de for ordering a new burner. For this you need the model, product- and serialnumber of the fridge.

Please send your invoice and the warranty service order (look at page 2) to Dometic GmbH, attn. to Mrs. Schöler, In der Steinwiese 16, 57074 Siegen, Germany.

You will get 50,00 Euro net for the exchange.

Please scrap the old burners directly. You will confirm the scrapping with the invoice.



