




GLASS DOOR HINGE REPLACEMENT

DESCRIPTION:

Due to problem with glass door tilting down door hinge 1366253217 is no longer available. It has been replaced by new door hinge and front panel set.

Attempt to fit new hinge in old front panel will cause deformation of panel.



SOLUTION:

Old door hinge must be replaced by set of new hinge and new front panel.

Old door hinge	Old front panel	New front panel and door hinge Kit
1366253209 1366253217	1367004007	4055344131
	1367004023	
	1367004049	
	1367004056	4055306585
	1367004080	
	1367004320	
	1367004411	
		4055306593
		4055280756

MODELS INVOLVED:

All Tumble Dryers with glass door.

REVISION:

Revision	Date	Description	Author	Approved by - on
03	03/2017	1366253209 added	Krzysztof Łazowski	
02	06/2015	KIT code updated	Krzysztof Łazowski	
01	02/2015	Added old front panels	Krzysztof Łazowski	Marcin Bernacki – 31.03.2015
00	12/2014	Document Creation	Krzysztof Łazowski	Marcin Bernacki – 10.12.2014