

**PUMP PRIMING****MODELS:** BUILT-IN SUPERAUTOMATIC COFFEE MACHINES- all the models**DATE:** 2015-01**DESCRIPTION:**

We inform you that in the above mentioned coffee machines models is been found **a possible problem regarding the first pump priming which may fail to start.**

This fault can occur in recently produced models as well as in older machines stocked for a long period in the warehouse.

If the problem occurs, you can activate the appliance by starting a new hot water delivery.

In case this procedure will not be successful, you need to disconnect the water tube from the pump and run it (in loads test procedure activated) to deliver hot water.

In order to definitely solve this pump priming problem, starting from

**25.05.2012**

all the pumps will be assembled after a longer washing, with the aim to remove all grease deposits.

We therefore invite you to carefully take into consideration this technical warning in case of problems during the first pump priming.

As a result you can achieve a faster and more effective repairing service.

Revision	Date	Description	Author	Approved by - on
00	01/2015	Document Creation	Blanka Kucharska	B.K. 2015-01