

# SERVICE BULLETIN DRYING

DRUM'S CONE BASE REPLACEMENT

### **DESCRIPTION:**

Drum's cone base 1366237004 is no longer available. It can be replaced by set of new cone base and back panel.

# **SOLUTION:**

Drum cone base 1366237004 can be replaced by set of new cone base and back panel.

Old drum cone base Old back panel		New drum cone base and back panel Kit	
1366237004	1366005021 (TDC)	4055325072	
	1366005419 (HP)	4055325080	

# **MODELS INVOLVED:**

All Tumble Dryers which have been equipped with drum's cone base 1366237004.

### **REVISION:**

Revision	Date	Description	Author	Approved by - on
00	02/2015	Document Creation	Krzysztof Łazowski	Marcin Bernacki – 17.02.2015