

DEFECTS IN COOKER WITH ELECTRONIC TIMERS AND OVERHEATING PROTECTION

DESCRIPTION:

From analysis of QES records of electronic timers replaced in service and sent back to factory, we found that most of timers are working correctly, without faults.

Serial numbers affected: 410XXXXX-444XXXXX

In case of one of more of following problems arise:

- display not working or turns off
- display flashes or flashes with "0"
- oven not working, turns off, turns off from time to time
- oven not heating

Most probably the faulty overheating thermostat is the reason of switching off the display. Therefore electronic timer operating must to be verified as described below.

SOLUTION:

In order to verify the electronic timer operating, please take out the overheating thermostat from circuit, make direct connection between wires (short circuit between overheating thermostat terminals) and verify if the electronic timer works.

In case the timer works overheating thermostat need to be exchanged. The overheating thermostat is connected between terminal block and timer. New thermostat must be mounted in the same way as old thermostat.



1. Old thermostat before exchange



2. New thermostat after exchange

SPARE PART NUMBER:

| Old spare part code | New spare part code | Description |
|---------------------|---------------------|-----------------------------------|
| 807459507 | 330208112 | overheating protection thermostat |

INTERCHANGEABILITY:

Thermostat 330208112 is fully interchangeable with 807459507

MODELS INVOLVED:

**LIST OF PNCs' FITTED WITH OVERHEATING THERMOSTAT ANC 8074595078
 COOKERS SERIAL NUMBER FROM 410XXXXX-444XXXXX
 (FROM WEEK 10.2014 UNTIL WEEK 44.2014 INCLUDED)**

| # | PNC | Production Date | RANGE |
|----|-------------|-----------------|------------|
| 1 | 94300422601 | 20130515 | FCM660MWC |
| 2 | 94300422602 | 20140410 | FCM660MWC |
| 3 | 94300423602 | 20130219 | EKC54500OW |
| 4 | 94300424003 | 20130219 | EKC54502OW |
| 5 | 94300424103 | 20130220 | EKC54502OK |
| 6 | 94300426103 | 20131218 | EKK54500OW |
| 7 | 94300426203 | 20140108 | EKK54500OW |
| 8 | 94300427502 | 20130221 | EKC54503OW |
| 9 | 94300427602 | 20130221 | EKC54503OS |
| 10 | 94300429400 | 20121218 | EKC54504OX |
| 11 | 94300430403 | 20131218 | EKK54503OW |
| 12 | 94300430503 | 20131217 | EKK54503OW |
| 13 | 94300430603 | 20140108 | EKK54503OW |
| 14 | 94300432603 | 20130320 | 47035VD-WN |
| 15 | 94300432702 | 20130320 | 47005VC-WN |
| 16 | 94300432802 | 20130328 | 47005VC-MN |
| 17 | 94300432903 | 20130320 | 47035VD-MN |
| 18 | 94300433002 | 20140122 | 47345GM-WN |
| 19 | 94300433101 | 20130429 | 47345GM-WN |
| 20 | 94300433702 | 20130219 | 47335GM-WN |
| 21 | 94300433704 | 20140407 | 47335GM-WN |
| 22 | 94300433802 | 20121002 | 47335GM-MN |
| 23 | 94300433804 | 20140408 | 47335GM-MN |
| 24 | 94300435602 | 20130822 | 47635GM-MN |
| 25 | 94300435702 | 20130320 | 47635GM-WN |
| 26 | 94300435803 | 20140320 | 47645GM-MN |
| 27 | 94300435903 | 20140303 | 47645GM-WN |
| 28 | 94300436202 | 20130320 | 47055VD-WN |
| 29 | 94300436303 | 20131106 | 47055VD-MN |
| 30 | 94300436705 | 20140109 | 4703RVD-MN |
| 31 | 94300436803 | 20130328 | 4703RVD-WN |
| 32 | 94300437601 | 20130218 | FCM661MW |
| 33 | 94300438701 | 20131112 | EKC54500OX |
| 34 | 94300438801 | 20131129 | EKC54501OX |
| 35 | 94300438901 | 20131105 | EKC54502OX |
| 36 | 94300439703 | 20140131 | EKK54500OX |
| 37 | 94300439803 | 20140212 | EKK54500OX |
| 38 | 94300439903 | 20140108 | EKK54500OX |
| 39 | 94300440103 | 20140130 | EKK54501OX |

| | | | |
|----|-------------|----------|------------|
| 40 | 94300440303 | 20131219 | EKK54501OX |
| 41 | 94300440803 | 20140130 | EKK54502OX |
| 42 | 94300441003 | 20131218 | EKK54502OX |
| 43 | 94300441203 | 20131218 | EKK54503OX |
| 44 | 94300441303 | 20131218 | EKK54503OX |
| 45 | 94300441601 | 20140129 | 47005VC-MN |
| 46 | 94300441801 | 20131106 | 47035VD-MN |
| 47 | 94300442002 | 20140108 | 47345GM-MN |
| 48 | 94300442102 | 20131218 | 47345GM-MN |
| 49 | 94300442202 | 20140221 | 47345GM-MN |
| 50 | 94300444900 | 20130226 | 47055VD-W8 |
| 51 | 94300445200 | 20130320 | HF56142 |
| 52 | 94300445400 | 20130610 | FCM663MW |
| 53 | 94300445600 | 20130328 | FCV664MWC |
| 54 | 94300445601 | 20130826 | FCV664MWC |
| 55 | 94300445701 | 20130902 | FCV664MSC |
| 56 | 94300445900 | 20130328 | EKC54300OW |
| 57 | 94300446000 | 20130328 | EKC54300OS |
| 58 | 94300448900 | 20131101 | ZCM65301WA |
| 59 | 94300448902 | 20140428 | ZCM65301WA |
| 60 | 94300448904 | 20141208 | ZCM65301WA |
| 61 | 94300450100 | 20130905 | ZCV955301W |
| 62 | 94300450201 | 20131026 | ZCV955301X |
| 63 | 94300450300 | 20130805 | ZCK955301W |
| 64 | 94300450400 | 20130911 | ZCK955301X |
| 65 | 94300450500 | 20130909 | ZCK955311W |
| 66 | 94300450600 | 20130909 | ZCK955311X |
| 67 | 94300451000 | 20130806 | EKC954500W |
| 68 | 94300451100 | 20130806 | EKC954500X |
| 69 | 94300451200 | 20130806 | EKC954501X |
| 70 | 94300451300 | 20130806 | EKC954502K |
| 71 | 94300451400 | 20130806 | EKC954502W |
| 72 | 94300451500 | 20130806 | EKC954502X |
| 73 | 94300452303 | 20131218 | EKK54504OX |
| 74 | 94300452700 | 20130806 | EKC954504W |
| 75 | 94300452800 | 20130805 | EKC954505W |
| 76 | 94300453301 | 20140107 | EKK954500W |
| 77 | 94300453401 | 20140220 | EKK954501X |
| 78 | 94300453501 | 20140129 | EKK954502X |
| 79 | 94300453601 | 20140107 | EKK954503W |
| 80 | 94300453701 | 20140131 | EKK954503X |
| 81 | 94300453801 | 20140108 | EKK954500X |
| 82 | 94300453900 | 20130611 | 47646GT-WN |
| 83 | 94300454000 | 20130614 | 47646GT-MN |

| | | | |
|-----|-------------|----------|------------|
| 84 | 94300454100 | 20130823 | ZCV65301WA |
| 85 | 94300454102 | 20140526 | ZCV65301WA |
| 86 | 94300454200 | 20130924 | ZCV65311XA |
| 87 | 94300454202 | 20140729 | ZCV65311XA |
| 88 | 94300454301 | 20140106 | ZCK55301WA |
| 89 | 94300454401 | 20131202 | ZCK55301XA |
| 90 | 94300457200 | 20140320 | FCM65301WA |
| 91 | 94300457400 | 20140317 | FCV6530CSA |
| 92 | 94300457500 | 20140317 | FCV6530CWA |
| 93 | 94300458300 | 20140417 | EKC954506W |
| 94 | 94300458400 | 20140520 | EKC954506X |
| 95 | 94300458500 | 20140417 | EKC954507X |
| 96 | 94300458600 | 20140418 | EKC954508K |
| 97 | 94300458700 | 20140417 | EKC954508W |
| 98 | 94300458800 | 20140418 | EKC954508X |
| 99 | 94300458900 | 20140417 | EKC954509W |
| 100 | 94300459000 | 20140417 | EKC954510W |
| 101 | 94300459600 | 20140612 | EKK954504W |
| 102 | 94300459700 | 20140611 | EKK954505X |
| 103 | 94300459800 | 20140611 | EKK954506X |
| 104 | 94300459900 | 20140613 | EKK954507W |
| 105 | 94300460000 | 20140613 | EKK954507X |
| 106 | 94300460100 | 20140611 | EKK954504X |
| 107 | 94300461200 | 20140404 | 47005V9-MN |
| 108 | 94300461300 | 20140404 | 47005V9-WN |
| 109 | 94300461500 | 20140409 | 4703RV9-MN |
| 110 | 94300461700 | 20140508 | 4713RV9-WN |
| 111 | 94300461800 | 20140404 | 47055V9-MN |
| 112 | 94300461900 | 20140409 | 47055V9-WN |
| 113 | 94300462000 | 20140813 | 47335G9-MN |
| 114 | 94300462100 | 20140813 | 47335G9-WN |
| 115 | 94300462200 | 20140409 | 47635G9-MN |
| 116 | 94300462300 | 20140409 | 47635G9-WN |
| 117 | 94300462400 | 20140409 | 47645G9-MN |
| 118 | 94300462500 | 20140409 | 47645G9-MN |
| 119 | 94300465900 | 20140814 | 47095VC-MN |
| 120 | 94300466000 | 20140814 | 47095VC-WN |
| 121 | 94300466100 | 20140315 | 47095VD-MN |
| 122 | 94300466200 | 20140315 | 47095VD-WN |
| 123 | 94300466300 | 20140315 | 47995VD-MN |
| 124 | 94300466400 | 20140315 | 47995VD-WN |
| 125 | 94300466500 | 20140315 | 47095VD-W8 |
| 126 | 94300466600 | 20140407 | 47395GM-MN |
| 127 | 94300466700 | 20140407 | 47395GM-MN |

| | | | |
|-----|-------------|----------|------------|
| 128 | 94300466701 | 20150428 | 47395GM-MN |
| 129 | 94300466800 | 20140407 | 47395GM-MN |
| 130 | 94300466900 | 20140407 | 47395GM-WN |
| 131 | 94300466901 | 20150428 | 47395GM-WN |
| 132 | 94300467400 | 20140911 | 47696GT-WN |
| 133 | 94300467500 | 20140321 | 47696GT-MN |
| 134 | 94300467900 | 20140418 | EKC54550OW |
| 135 | 94300468000 | 20140328 | EKC54550OX |
| 136 | 94300468100 | 20140417 | EKC54551OX |
| 137 | 94300468200 | 20140417 | EKC54552OK |
| 138 | 94300468300 | 20140417 | EKC54552OW |
| 139 | 94300468400 | 20140418 | EKC54552OX |
| 140 | 94300468500 | 20140328 | EKC54553OS |
| 141 | 94300468600 | 20140328 | EKC54553OW |
| 142 | 94300470300 | 20140407 | EKK54550OW |
| 143 | 94300470400 | 20140408 | EKK54550OW |
| 144 | 94300470500 | 20140407 | EKK54550OX |
| 145 | 94300470600 | 20140407 | EKK54550OX |
| 146 | 94300470700 | 20140407 | EKK54550OX |
| 147 | 94300470800 | 20140408 | EKK54551OX |
| 148 | 94300470900 | 20140408 | EKK54551OX |
| 149 | 94300471000 | 20140407 | EKK54552OX |
| 150 | 94300471100 | 20140327 | EKK54552OX |
| 151 | 94300471200 | 20140407 | EKK54553OW |
| 152 | 94300471300 | 20140407 | EKK54553OW |
| 153 | 94300471400 | 20140327 | EKK54553OW |
| 154 | 94300471500 | 20140407 | EKK54553OX |
| 155 | 94300471600 | 20140327 | EKK54553OX |
| 156 | 94300471700 | 20140327 | EKK54554OX |
| 157 | 94300472200 | 20140324 | EKC54350OW |
| 158 | 94300472300 | 20140324 | EKC54350OS |
| 159 | 94300472700 | 20140417 | 4713RV9-MN |
| 160 | 94300472900 | 20140507 | EKC954301W |
| 161 | 94300473000 | 20140507 | EKC954301X |
| 162 | 94300473100 | 20140808 | EKK54555OX |
| 163 | 94300473200 | 20140407 | EKK54554OW |
| 164 | 94300473300 | 20140324 | EKK54556OX |
| 165 | 94300475700 | 20140918 | HF561421 |

REVISION:

| Revision | Date | Description | Author | Approved by - on |
|----------|---------|-------------------|-------------|------------------|
| 00 | 04/2015 | Document Creation | Tomasz Hyży | Stefan Tripon |