




Back panel change in Vented Tumble Dryer

DESCRIPTION:


Old type of back panel, spare part number 1254265174, is no longer available. It can be replaced by new one but also power cable with filter has to be exchanged.

SOLUTION:

Old back panel can be replaced by assembly of new panel and new power cable with filter.



1. Old back panel terminal hole.



2. New back panel terminal hole.

SPARE PART NUMBER:

Plug type	Length [mm]	Old spare part code	New spare part code		
		Back panel	Back panel	Power cable with filter	Length [mm]
ARG	2100	1254265109 1254265125 1254265141 1254265158 1254265174	1254265315	N/A	
AUS	2450			1364090611	2450
BRA	2000			N/A	
CHE	2200			1364090512	2100
EUR	2000			1364090116	1500
GBR	2100			1364090405	1500
THA	1700			N/A	
ZAF	2000			N/A	

REVISION:

Revision	Date	Description	Author	Approved by – on
00	06/2015	Document Creation	Krzysztof Łazowski	Marcin Bernacki – 26.06.2015