



REPAIR OF APPLIANCES WITH USER INTERFACES 140000453013 AND 140000453039

DESCRIPTION:

We would like to inform you that user interfaces EDW503, 140000453013 and 140000453039 are no longer available. Due to incompatibility with old PB200 there are two solutions prepared:

1. In case of Sidekick Users it is necessary to order new version of user interface and reprogram the main power board
(* Before reprogramming the main power board, please update Sidekick software.)
2. In case of Non- Sidekick Users instead of user interface please order 973* code for PB200 (according to spare part list). This code contains new version of user interface and configured electronics with updated software.

For PB200 defects:

1. In case of Sidekick Users apart from power board it is necessary to order new version of user interface
2. In case of Non- Sidekick Users it is not necessary to order any additional spare parts. 973* includes all parts which are needed to repair an appliance.

SPARE PART NUMBER:

Old spare part code	New spare part code	Description
140000453039	140000453096	User interface board, EDW503
140000453013	140000453070	User interface board, EDW503

REVISION:

Revision	Date	Description	Author	Approved by - on
00	09/2015	Document Creation	Marcin Łapa	Piotr Banasik