



### Water leakage through gap between lid and hopper.

#### DESCRIPTION:

In some appliances, hopper deforms in door lock area. It causes water leakage through gap between lid and hopper.




Photo1. Hopper deformation.

#### SOLUTION:

Replace lid gasket and hopper. Components are available in kit 4055367710.

#### MODELS INVOLVED:

Problem can occur in following appliances with Soft Opening lid:

| PNC_ELC     | Model      |
|-------------|------------|
| 91321628105 | EWT126450W |
| 91321635104 | EWT136450W |
| 91321641105 | EWT135210W |
| 91321644106 | EWT105510W |
| 91321694103 | EWT136459W |
| 91321700401 | L70360TL   |
| 91321700402 | L70360TL   |
| 91321700501 | L70268TL   |
| 91321701102 | L86560TL   |

| PNC_ELC     | Model      |
|-------------|------------|
| 91321701501 | L70360TL   |
| 91321701502 | L70360TL   |
| 91321701601 | L70260TL   |
| 91321701602 | L70260TL   |
| 91321702201 | L70269TL   |
| 91321704003 | EWT105514W |
| 91321704603 | EWT135510W |
| 91321704801 | EWT136414W |
| 91321705101 | EWT116212W |

| PNC_ELC     | Model      |
|-------------|------------|
| 91321705201 | EWT116210W |
| 91321705601 | L70360TL   |
| 91321705602 | L70360TL   |
| 91321705701 | EWT106414W |
| 91321706001 | EWT106411W |
| 91321706101 | EWT136411W |
| 91321706201 | EWT106511W |
| 91321706301 | EWT136511W |
| 91321706401 | EWT136551W |

| PNC_ELC     | Model      |
|-------------|------------|
| 91321706501 | EWT126451W |
| 91321706701 | RWT126451W |
| 91321706801 | EWT136451W |
| 91321707001 | EWT136414W |
| 91321707601 | EWT136410W |
| 91321707701 | EWT136418W |
| 91321707901 | RWL106411W |
| 91321708001 | RWT116211W |
| 91321708801 | L70260TL   |
| 91321709501 | L86560TL3  |
| 91321710101 | WASL3T200  |
| 91321710201 | WAGL2T200  |
| 91321710301 | EWT146511W |
| 91321710401 | EWT136511W |
| 91321710501 | EWT126451W |
| 91321710601 | EWT136451W |
| 91321710900 | EWT136451W |
| 91321710901 | EWT136451W |
| 91321711101 | L70260TL   |
| 91321711801 | EWT126215W |
| 91321711901 | EWT136215W |
| 91321712201 | EWT106411W |
| 91321712501 | L76465TL3  |
| 91321712601 | EWT136541W |
| 91321712701 | EWT106211W |
| 91321712801 | EWT106411W |
| 91321712901 | EWT106511W |
| 91321713001 | EWT136411W |
| 91321713101 | EWT136511W |
| 91321713501 | EWT106211W |
| 91321713702 | L76265TL3  |
| 91321713802 | L76269TL3  |
| 91321713901 | L86369TL3  |
| 91321714101 | EWT106211W |
| 91321714201 | EWT106211W |
| 91321714301 | EWT106211W |
| 91321714401 | EWT106211W |
| 91321714501 | EWT106211W |
| 91321714601 | EWT136541W |
| 91321714701 | RWT136543W |
| 91321714801 | EWT136541W |
| 91321715001 | EWT136641W |
| 91321715101 | EWT136641W |
| 91321715201 | L76460TL3  |
| 91321715501 | L70260TLP  |

| PNC_ELC     | Model      |
|-------------|------------|
| 91321715502 | L70260TLP  |
| 91321716301 | EWT106417W |
| 91321716600 | EWT106411W |
| 91321716601 | EWT106411W |
| 91321716700 | EWT126451W |
| 91321716701 | EWT126451W |
| 91321716901 | EWT106511W |
| 91321717901 | L86360TL3  |
| 91321718201 | L70260TL   |
| 91321718601 | L76460TL3  |
| 91321719801 | EWT126451W |
| 91321720200 | EWT1567VDW |
| 91321720201 | EWT1567VDW |
| 91321720400 | EWT1366HDW |
| 91321720401 | EWT1366HDW |
| 91321720500 | EWT1466HDW |
| 91321720501 | EWT1466HDW |
| 91321722100 | EWT1367VDW |
| 91321722101 | EWT1367VDW |
| 91321722400 | EWT1366HDW |
| 91321722401 | EWT1366HDW |
| 91321722800 | EWT1367VDW |
| 91321722801 | EWT1367VDW |
| 91321722900 | EWT1567VDW |
| 91321723200 | EWT1567VDW |
| 91321723400 | EWT1366HDW |
| 91321723401 | EWT1366HDW |
| 91321724300 | EWT1567VDW |
| 91321724301 | EWT1567VDW |
| 91321725100 | EWT1466HDW |
| 91321725700 | RWT1367VDW |
| 91321726400 | EWT1066EEW |
| 91321726500 | EWT1067EDW |
| 91321726600 | EWT1367EDW |
| 91321727600 | EWT1466HDW |
| 91321727601 | EWT1466HDW |
| 91321729200 | EWT1366HZW |
| 91321729201 | EWT1366HZW |
| 91321729500 | L76264ATL  |
| 91321730300 | L75460TL1  |
| 91321730301 | L75460TL1  |
| 91321730900 | L70260TL1  |
| 91321731000 | L70269TL1  |
| 91321731100 | L70360TL1  |
| 91321731200 | L75265TL1  |

| PNC_ELC     | Model      |
|-------------|------------|
| 91321731201 | L75265TL1  |
| 91321731300 | L75269TL1  |
| 91321731301 | L75269TL1  |
| 91321731400 | L75465TL1  |
| 91321731401 | L75465TL1  |
| 91321731500 | L75460TL1  |
| 91321731600 | L86360TL4  |
| 91321731700 | L86360TL4  |
| 91321731800 | L86369TL4  |
| 91321731801 | L86369TL4  |
| 91321731900 | L86355TL5  |
| 91321731901 | L86355TL5  |
| 91321732000 | L86565TL4  |
| 91321732001 | L86565TL4  |
| 91321732400 | L70360TL1  |
| 91321732500 | L75469TL1  |
| 91321732501 | L75469TL1  |
| 91321732600 | L86560TL4  |
| 91321732601 | L86560TL4  |
| 91321732700 | L75268TL1  |
| 91321732701 | L75268TL1  |
| 91321732800 | L86560TL4  |
| 91321732801 | L86560TL4  |
| 91321732900 | L70260TL1  |
| 91321732901 | L70260TL1  |
| 91321733000 | L75460TL1  |
| 91321733100 | L86560TL4  |
| 91321733101 | L86560TL4  |
| 91321734300 | L76254ETL  |
| 91321734500 | WAGL2T201  |
| 91321734501 | WAGL2T201  |
| 91321734600 | WASL3T201  |
| 91321734601 | WASL3T201  |
| 91321735200 | L70360TL1  |
| 91321735300 | L86360TL4  |
| 91321735301 | L86360TL4  |
| 91321735700 | EWT1368VDW |
| 91321735800 | EWT0866EEW |
| 91321735900 | EWT1062EFW |
| 91321736500 | EWT106415W |
| 91321736700 | L75460TL1  |
| 91321736701 | L75460TL1  |
| 91321736800 | EWT1360HYW |
| 91321736801 | EWT1360HYW |
| 91321737400 | L86560TL4  |

| PNC_ELC     | Model      | PNC_ELC     | Model      | PNC_ELC     | Model      |
|-------------|------------|-------------|------------|-------------|------------|
| 91321737401 | L86560TL4  | 91321743500 | RWT1377VDW | 91321747700 | L70265TLC  |
| 91321737500 | L75260TL1  | 91321743501 | RWT1377VDW | 91321747800 | L70265TL   |
| 91321737501 | L75260TL1  | 91321743600 | EWT1377VOW | 91321748900 | EWT1376HLW |
| 91321737600 | L70260TL1  | 91321743601 | EWT1377VOW | 91321748901 | EWT1376HLW |
| 91321737900 | L86560TLP4 | 91321743800 | EWT1377VOW | 91321750900 | L74270TL   |
| 91321737901 | L86560TLP4 | 91321743801 | EWT1377VOW | 91321751000 | L5.5TL     |
| 91321738000 | L75260TLP1 | 91321744000 | L71260TL   | 91321751100 | L71269TL   |
| 91321738001 | L75260TLP1 | 91321744001 | L71260TL   | 91321751101 | L71269TL   |
| 91321738100 | L70260TLP1 | 91321744200 | L71270TL   | 91321751200 | L7726PTL   |
| 91321738700 | EWT1062EFW | 91321744201 | L71270TL   | 91321751600 | L74270TL   |
| 91321738800 | EWT1066EEW | 91321744400 | L74270TL   | 91321751800 | L75370TL   |
| 91321738900 | L70260TLC1 | 91321744500 | L74270TL   | 91321752300 | EWT1376HLW |
| 91321739000 | L75260TLC1 | 91321744600 | L74270TLE  | 91321752500 | L75370TL   |
| 91321739001 | L75260TLC1 | 91321744700 | L74270TLP  | 91321752700 | L57126TL   |
| 91321739700 | L86560TLE1 | 91321744800 | L74270TLC  | 91321752900 | L71260TLC  |
| 91321739701 | L86560TLE1 | 91321744900 | L74270TL   | 91321753000 | L71260TLP  |
| 91321739800 | L75260TLE1 | 91321745100 | L74270TL   | 91321753100 | L71260TL   |
| 91321739801 | L75260TLE1 | 91321745200 | L75370TLE  | 91321753500 | L70260TL1  |
| 91321739900 | L70260TLE1 | 91321745400 | L85370TL   | 91321753501 | L70260TL1  |
| 91321740800 | L70260TL1  | 91321745500 | L585370TL  | 91321753600 | ML6351     |
| 91321740900 | ML6350     | 91321745600 | L87375TL   | 91321753700 | EWT1375DDW |
| 91321741100 | L75260TL1  | 91321745700 | L87379TL   | 91321754000 | EWT1266ODW |
| 91321742000 | EWT11266AW | 91321745800 | L75279TL   | 91321754100 | EWT11266OW |
| 91321742100 | EWT1266AOW | 91321745900 | L75278TL   | 91321754200 | EWT1276GDW |
| 91321742400 | RWT1276EDW | 91321746000 | L71360TL   | 91321754700 | L71270TL   |
| 91321742500 | EWT1276EOW | 91321746001 | L71360TL   | 91321754701 | L71270TL   |
| 91321742600 | EWT11276EW | 91321746200 | L7527TL    | 91321754900 | LÖKO+++TL  |
| 91321742601 | EWT11276EW | 91321746300 | L75275TL   | 91321755000 | L87370TL   |
| 91321742700 | EWT31276EW | 91321746700 | L70260TL1  | 91321755200 | EWT1276EDW |
| 91321742900 | EWT1276EOW | 91321747000 | EWT1276EOW | 91321755300 | EWT1377VDW |
| 91321743000 | EWT1276EOW | 91321747200 | EWT1266AOW | 91321755400 | EWT1266ODW |
| 91321743200 | EWT1376EOW | 91321747300 | EWT1266AOW | 91321755500 | L74270TL1  |
| 91321743400 | RWT1076ODW | 91321747500 | EWT1276EOW | 91321755800 | LPFLEGE+TL |
| 91321743401 | RWT1076ODW | 91321747600 | L70265TLP  |             |            |

**REVISION:**

| Revision | Date    | Description       | Author             | Approved by - on          |
|----------|---------|-------------------|--------------------|---------------------------|
| 00       | 05/2016 | Document Creation | Krzysztof Łazowski | Henri Chemin – 19.05.2016 |