


SERVICE BULLETIN

COOKING

Elimination of Blanking Button in New Production


Presently we have Blanking Buttons (White Caps) on alternate terminals of the Terminal block to prevent incorrect connection.

- 1. Blanking Buttons
- 2. Terminal Block



Future Production will eliminate these Blanking Buttons. When removal is required for service operation note the correct connections. The connection plate is adhered to the rear panel.

- 3. Unfasten the screws
- 4. Remove the connection cover.
- 5. To assist correct connection
 - a. Refer to the adhered Electrical connection label
 - b. Use Cable tags
 - c. Photograph the connections for reference.



Revision	Date	Description	Approved by
0.0	04/2017	Document creation	Ireneusz Zapala