


Gas Hob-Flush Burner Spillage

DESCRIPTION:

In case of accidental spillages over the hob surface, liquids may overflow under the appliance.

SOLUTION:


To add a graphite gasket between the burner body and the hob panel/plate as described below:




1. Remove the hob panel



2. Add the gasket on the burner according to the size/shape



3. Assemble all gaskets



4. Reassemble the hob panel

SPARE PART NUMBER:

Old spare part code	New spare part code	Description
N/A	140129831016	Graphite gasket kit

QES CODE:

During the intervention please use work code 11 and:

Component	506
Defect	11

MODELS INVOLVED:

Flush Burners hobs

REVISION:

Revision	Date	Description	Author	Approved by - on
00	11/2017	Document Creation	BSP	Gabriele Brandoli