

SERVICE BULLETIN COOKERS

FS COOKERS FITTED WITH THERMOSTAT TECASA TO BE REPLACED WITH THERMOSTAT EGO

DESCRIPTION:

FS Cookers fitted with oven electric thermostat TECASA ANC: 807490201/807490203 stop working due to ceramic button broken inside.



SOLUTION:

FS Cookers fitted with Oven electric thermostat TECASA to be replaced with oven electric thermostat EGO When order spare part please order ANC: 3890777067 instead of ANC: 8074902019 listed in TDS spare part list

SPARE PART NUMBER:

To use spare part number EGO thermostat ANC: 3890777067

QES CODE:

Use the following QES Code during the investigation

Component	405
Defect	21

REVISION:

Revision	Date	Description	Author	Approved by - on
00	04/2018	Document Creation	Monica Mihalca	
01	04/2018	Document editedPNC table deleted	BSP	

EN 1/1 599 8183-50 Rev.01