



AUTO-OFF FUNCTION / STANDBY MODE

DESCRIPTION:

The dryer after finishing the cycle (program + anti-crease phase) does not have auto-off function (did not pass the standby mode)

Auto-off function / standby mode = LCD backlight or leds are active

SOLUTION:

To solve this issue a Software update in the main board has to be performed.

IMPORTANT: Update Sidekick before performing this action to have the latest required update available.

QES CODE:

During the intervention please use work codes:

Component	G45 607 Main control PCB
Defect	G45 31 Software fault

In the section for Tech. Comments insert: **Main board software update to solve auto-off function /stand by mode – SB no.: 599 82 42-74.**

MODELS INVOLVED:

Tumble Dryer Vented (**TDV**) and Tumble Dryers Condense (**TDC**) based on the platforms:

- **ENV06**

REVISION:

Revision	Date	Description	Author	Approved by - on
00	10/2018	Document Creation	Marcin Pluta	Marek Kapustka 22.10.2018